



U.S. Department  
of Transportation  
**Research and  
Special Programs  
Administration**

400 Seventh Street, S.W.  
Washington, D.C. 20590

NOV 12 2002

Mr. John Freiler  
Girard Equipment, Inc.  
1004 Route 1  
Rahway, NJ 07065

Ref. No. 01-0295

Dear Mr. Freiler:

This is in response to your November 9, 2001 letter and subsequent conversations with members of my staff requesting clarification on the replacement of vents on MC 300 series cargo tanks with vents designed for DOT 400 series cargo tanks meeting the performance requirements of § 178.345-10(b)(3) in the Hazardous Materials Regulations (HMR; 49 CFR Parts 171-180). In addition to clarifying RSPA's position on this issue, you also request that RSPA allow 25 psig maximum allowable working pressure (MAWP) MC 307 tanks to have their vents upgraded to DOT 407 vents having a set pressure of 30 psig as required by the requirements for DOT 407 vents as described in § 178.345-10. I apologize for the delay in responding to your letter.

The interpretation issued by this office by Hattie Mitchell in 1996 is correct. Section 173.33(d)(3) requires the replacement DOT 407 series valve only to meet the original MC 307 cargo tank venting capacity requirements. Thus, the letter to Bill Quade (Ref. No. 01-0247) should be amended to clarify that only the venting capacity requirements for the 300 series tank need be met.

In addition, your request to allow MC 307 cargo tanks with a maximum allowable working pressure (MAWP) of 25 psig to have their vents upgraded to DOT 407 vents having a set pressure of 30 psig (as required in § 178.345-10 for DOT 407 vents) must be submitted as a petition for rulemaking under the requirements of § 106.31 in order for RSPA to consider a rule change.

We hope this satisfies your request.

Sincerely,

Robert A. McGuire  
Associate Administrator  
Office of Hazardous Materials Safety



010295

178.345-10

February 13, 2002

John Freiler  
Engineering Manager  
Girard Equipment, Inc.  
1004 US Route 1  
Rahway, NJ 07065  
Ph: 1-800-526-4330 ext. 618  
Fax: (732) 382-4650  
E-mail: [jfreiler@girardequip.com](mailto:jfreiler@girardequip.com)

Michael Johnson  
Tr. Reg. Spec.  
Standards Development, DHM-11  
Fax: (202) 366-3012

Dear Mr. Johnson;

Thank you for returning my phone call and discussing my November 9, 2001 letter.

During that conversation, we uncovered some confusion with the second to last paragraph in my letter:

In light of these points, I ask if you could revisit your answer and change it to allow 25 psig MAWP MC 307 tanks to have their vents upgraded to DOT 407 vents having a set pressure of 30 psig as required by the requirements for DOT 407 vents as laid out in 178.345-10.

It is important to note the word "set pressure". The DOT 407 vent I'm referring to would be set nominally at 30 psig and could be set as high as 33 psig as per the requirements of 49CFR§178/345-10(d)(1):

*Settings of pressure relief system...*

*Primary pressure relief system.* The set pressure of each primary pressure relief valve must be no less than 120 percent of the MAWP, and no more than 132 percent of the MAWP. ...

So for the 25 psi MAWP MC 307 tank in question, a DOT 407 venting system would have to be set at no less than 120% of 25 psig or 30 psig and no more than 132% of 25 psig or 33 psig.

So, a DOT 407 vent having a set pressure of 30 psig is a 25 psig DOT 407 vent.

I look forward to talking with you further on this subject on Thursday, February 21<sup>st</sup>.

Sincerely,



John Freiler

November 9, 2001

John Freiler  
Engineering Manager  
Girard Equipment, Inc.  
1004 US Route 1  
Rahway, NJ 07065  
Ph: 1-800-526-4330 ext. 618  
Fax: (732) 382-4650  
E-mail: jfreiler@girardequip.com

Delmer F. Billings  
Chief, Standards Development, DHM-11  
Fax (202) 366-3012

Dear Mr. Billings;

I have recently come into possession of a memorandum (Ref. No. 01-0247) from you to William Quade, Chief, Hazardous Materials Division, MC-ECH, which offers up some clarifications to the concerning cargo tank regulations in the Hazardous Materials Regulations (HMR; 49 CFR Parts 171-180).

I feel that the clarifications you offered up are in error, and would not only cause financial hardship and confusion, but would also create a safety hazard if they were to be enforced as written.

In your letter, you said:

- Q3. According to § 173.33(d)(3) the pressure relief system on a 300 series cargo tank may be upgraded to a pressure relief system meeting the requirements of a 400 series cargo tank, as long as "the venting capacity requirements of the original specification are met when the valve is modified." However, the methods for determining venting capacity are different for the 300 series and the 400 series cargo tanks. According to § 178.345-10(g) the 400 series pressure relief devices are typically tested and rated at 1.5 times MAWP. The MC-307 specification (§ 178.342-4) requires the devices to be tested at 130%. For a 300 series cargo tank that is equipped with a pressure relief device manufactured in accordance with 400 series requirements, at what pressure should the flow capacity be determined?
- A3. The flow capacity must be determined using the requirements of the original specification, as stated in § 173.33(d)(3). Therefore, in the example you included above, the DOT-407 vent used on an MC-307 cargo tank must be flow tested at 130% of the design pressure to accurately determine compliance with the minimum venting requirements of § 178.340-4. This information should be supplied by the valve manufacturer of the pressure relief device.

First I shall discuss why I feel this is in error. This same question arose in 1995 when an officer in the California Highway Patrol made the inquiry of me. I sent a request for clarification to your office and received a reply in a letter dated June 10, 1996 from Hattie L. Mitchell, then Chief of Exemptions and Regulations Termination OHMS that read as follows:

Dear Mr. Freiler:

This is in response to your letter requesting clarification of the pressure relief requirements specified in 49 CFR 173.33(d). Specifically, you asked if § 173.33(d)(3) prohibits upgrading vents on MC 307 and MC 312 cargo tanks to DOT 407 and DOT 412 vents that are flow rated in accordance with § 178.345-10. I apologize for the delay in responding and regret any inconvenience it may have caused.

The answer is no. Section 173.33(d)(3) provides that pressure relief devices or outlets on a specification cargo tank motor vehicle listed in column 1 may be modified to meet the applicable requirements for the specification listed in column 2. However, replacement devices constructed to the requirements of § 178.345-10 must provide the minimum venting capacity required by the original specification to which the cargo tank was design and constructed.

I trust this satisfies your inquiry.

Hattie L. Mitchell, Chief

Further, we should consider the intent under which the provision found in § 173.33(d)(3) "The venting capacity requirements of the original DOT cargo tank must be met whenever a pressure relief valve is modified" was inserted into the CFR. This provision was added to the code in response to comments made at public meetings that I attended. At those meetings, there was much concern expressed by vent makers in regard to the so-called "Smart Vent" or "Dual Function" requirements {the reduced leakage during surge requirements laid out in § 178.345-10 (b)(3)}. Betts Industries, a leading Manufacturer of vents for MC-306 cargo tanks had developed a style of vent for the DOT 406 requirements that would leak less than one gallon during surge, but those vents had a reduced capacity at the set and flow rate pressures for a DOT 406 cargo tank when compared to the vents currently in service on MC-306 tanks. It was felt that a potential safety hazard existed wherein a MC-306 cargo tank operator could replace his existing vents one for one with the new smart vents, not realizing that their capacity as measured at the DOT 406 pressures would be lower in terms of SCFH than that cargo tank originally required. This lead to the following entry in the Federal Register Vol. 59, No. 212, Thursday, November 3, 1994, pg. 55163 & 55169:

Page: 55163:  
Section 173.33

Consistent with the changes made in § 180.405(h) in this final rule, a new sentence is added to paragraph (d) stating that the venting requirements of the original DOT cargo tank

specification must be met whenever a pressure relief valve is modified to a more recent specification. See preamble discussion for § 180.405(h).

Page: 55169:  
Section 180.405

Paragraph (h) specifies that replacement for any pressure replacement for any reclosing pressure relief valve must be capable of re-seating to a leak-tight condition after a pressure surge. Section 180.405(e) authorizes modifying the reclosing pressure relief valves of an MC 306 cargo tank by installing the dual function pressure relief valves which are required for DOT406 cargo tank motor vehicles. Commentators pointed out that this replacement could result in an MC 306 cargo tank having lower emergency venting capacity than its specification requires: because it is difficult to produce a valve that achieves the comparatively high flow rates of the MC 306 units, withstands the pressure surges specified in the DOT 406 specification, and recloses with minimal loss of lading. A reduced flow capacity is less likely to be encountered in fitting and MC 307 with a DOT 407 valve replacement, and in fitting an MC 312 with a DOT 412 valve replacement, because of the larger pressure differentials which are commonly used in these cargo tanks. Regardless of the equipment installed, the venting requirements specified in the particular cargo tank specification must be met whenever a pressure relief valve is replaced. ...

Note that our company was the one queried as to the status of Vents available for DOT 407 and DOT 412 cargo tanks. No mention was made of a vent that was essentially a crippled DOT 407 or DOT 412 vent; one made to those specifications, but with flow rates made to the obsolete MC 307 or MC 312 specifications. Only "capacity" is referenced. Indeed, it is the DOT 407 and DOT 412 cargo tanks that have "larger pressure differentials" than their corresponding obsolete MC 307 or MC 312 specification.

Finally, in discussions with the Late Mr. Ron Kirkpatrick of your office (DHM-22) regarding the 1995 California Highway Patrol inquiry discussed previously, Mr. Kirkpatrick Faxed me the following letter Dated June 8, 1995:

**ANALYSIS OF VENTING OF MC 307 CARGO TANKS WITH DOT 407 PRESSURE RELIEF DEVICES INSTALLED.**

Both §§ 173.33(d)(3) and 180.405(c)(2) authorizes the modification of pressure relief devices and outlets on various MC 300-series cargo tanks to the related DOT 400-series specifications; the table in § 173.33(d)(3) clearly shows the specifications for which these modifications are authorized. For example, pressure relief devices on the MC 307 may be modified in accordance the DOT 407 specification.

In order to illustrate the steps required to carry out the MC 307 to DOT 407 venting modification, the DOT 407 type reclosing pressure relief valve (407PRV) would be installed and all parts of the MC 307 pressure relief system would have to be removed, i.e. each MC 307 type pressure relief system would have to be removed, and each fusible or frangible device. Non-reclosing pressure relief devices are not authorized in DOT 407 pressure relief systems except when in series with a reclosing pressure relief device, see § 178.345-10(b). In carrying out this modification, the total venting capacity required by § 178.342-4(b) must be maintained, as stated in § 180.405(h)(3). The number of 407 PRVs required to meet the total venting capacity for the MC 307 must be determined based on the area exposed (to fire), see § 178.342-4, Table III.

The venting capacity of the 407 PRV is rated at "not more than the tank test pressure", i.e. 1.5 MAWP. In the MC 307, "one or more device" shall provide "sufficient capacity to limit the tank internal pressure to a maximum of 130 percent" of MAWP. This can be accomplished using any combination of pressure actuated venting (spring loaded) (PAV), and fusible and/or frangible venting devices.

- The PAVs are required to have minimum venting capacity of 12,000 SCFH "measured at a pressure of 130 percent" of MAWP and the set pressure is given as "not less than" MAWP.

- Frangible devices are required to have burst pressures between 130 and 150 percent of MAWP.

- Fusible devices are required to have a minimum area of 1.25 sq. inches, and to operate at a temperature not exceeding 250°F "when the tank pressure is between" MAWP and 130 percent of MAWP.

A typical MC 307 designed for 25 psig MAWP would have one 3" PAV of about 27,000 SCFH capacity, with two 3" fusible devices provided to supply the additional emergency flow requirements.

In a fire situation, it is quite possible that the tank internal pressure could exceed 130 percent of MAWP before the fusibles opened. Similarly, if frangible devices were used to provide the bulk of the emergency flow rather than fusibles, internal pressures greater than 130 percent of MAWP could be anticipated under some circumstances.

Test pressure for MC 307 is 40 psig or a minimum of 1.5 MAWP whichever is greater, see § 178.342-7(a). At the minimum MAWP for this cargo tank, 25 psig, test pressure is 1.6 MAWP; at 26.67 psig and above, the test pressure is 1.5 MAWP. The 407 PRV develops rated flow capacities at 1.5 MAWP or less.

In view of these facts, and considering the following structural considerations:

- maximum calculated stress values must not exceed 20 percent of the minimum ultimate strength for non-ASME tanks, or about 25 percent of ultimate for ASME tanks, and
- emergency flow rates could be expected to be called for only under conditions where dynamic loading is extremely unlikely,

the installation of a DOT 407 pressure relief system on an MC 307 cargo tank will not compromise the structural integrity of the cargo tank.

*[Letter presented in its entirety]*

Note in the third paragraph, Mr. Kirkpatrick specifically addresses the fact that DOT 407 vents are flow rated at pressures different than those required for MC 307 vents. This reflects the view prevalent in the Office of Hazardous Materials Technology at that time, that during an upgrade in venting, the pressures at which the vents are flow rated are those to which the vent was constructed to, i.e. DOT 400-series, and not to the obsolete requirements of the MC 300-series as your memorandum Ref No. 01-0247 indicates.

Next, I will address the fact that this ruling, if enforced would result in financial hardship and confusion. Since 1991 through August 31, 1995, the vast majority of chemical transport cargo tanks produced were made to the MC 307 specification with DOT 407 venting as provided for in § 180.405(c)(2). We sold approximately 2,800 of our *DOT-407 Jet vents* in 1994 alone, during which time, we understand that the vast majority of which went on new-construction MC 307 cargo tanks. Also, from 1996 through to the present, many owners of MC 307 & MC 312 tanks have upgraded their tanks venting to DOT 407 & DOT 412 specifications so as to remove the need to maintain non-reclosing vents such as fusible and frangible devices. These tanks, which amount to many thousands of units are, to my knowledge, all equipped with venting that is both set-to-discharge and flow rated in accordance with the rules and regulations laid out for DOT 400-series tanks in §178.345-10. That is they are set-to-discharge at 120%-132% of MAWP and are flow rated at the tank test pressure, which is the maximum of 150% of MAWP or 40 psig. This has been the standard industry practice for a decade.

If the "clarifications" presented in your memo were to be enforced, it would necessitate the removal and replacement of many thousands of currently legal and safe pressure relief vents, while stalling vast amounts of commerce by making these many thousands of cargo tanks illegal for hazardous materials transport.

Another factor contributing to the confusion this would generate is the fact that absent the set-to-discharge and flow rating pressures, spring loaded pressure relief vents for MC 307 and DOT 407 vents do not differ at all. The DOT 400-series vents do call for a reduced leakage during surge capability in § 178.345-10(b)(3) which is not found in the original MC 307 venting requirements, but is retroactively applied to any new vent installed after August 31, 1998 in § 180.405(h)(2). So in essence, the code provides for upgrades in venting systems, but the "clarification" presented in your memo would remove the possibility: the only vents your clarification seems to allow are ones that comply in full with the MC 307 venting requirements and not at all with the unique requirements for DOT 407 tanks.

The only conclusion a cargo tank operator can come to is that upgrading is in fact not allowed and that they must immediately downgrade their tanks to the less safe venting systems presented in the obsolete MC 300 series code.

Finally, this "clarification" as presented in your memo would result in a safety hazard if enforced. The DOT 400 series venting requirements result in a safer tank than the obsolete MC 300-series requirements:

- The elimination of non-reclosing venting such as fusible and frangible devices when upgrading from MC 300-series to DOT 400-series venting results in greater levels of hazardous material product containment during emergency situations.

- The increase in set-to-discharge pressure from MAWP for MC 300-series venting to 120% of MAWP for DOT 400-series venting allows extra product retention capability during a rollover accident to account for static head of the product. For example, a product that produced a 25 psi vapor pressure hauled in a 25 pound tank would be fine so long as the tank remained upright. But if the tank rolled over, the vent, which would then be on the bottom of the tank, would be exposed not only to the 25 psi vapor pressure, but also to the pressure of the weight of the liquid over it. This would cause an MC 300-series vent to discharge hazardous liquids into the accident scene, while a DOT 400-series vent, by virtue of being set-to-discharge at 120% of 25 psi, will continue to safely retain the product.
- The requirements for vacuum relief in the DOT 400-series vents that are missing in the MC 300-series help eliminate dangers associated with cargo tank implosion, a common event in tanks not equipped with vacuum relief.

It should also be noted that DOT 400-series vents set and flow rated in accordance with the requirements for such vents in § 178.345-10 do not compromise the safety of an MC 300-series cargo tank:

- The conclusion of Mr. Ron Kirkpatrick's letter quoted above states that DOT 400-series venting will not compromise structural integrity of MC 300-series tanks to which they are installed.
- The rating of DOT 400-series vents at the tank test pressure is not a risk to safety since all cargo tanks in hazardous materials service are required to be physically tested to the test pressure on a regular basis of every one to five years as required by § 180.407(c), so we know that the tank is capable of withstanding these pressures without "leakage, bulging or other defect." See § 180.407(g)(1)(viii).
- There remains a large safety factor for the cargo tank as, absent the "leakage, bulge or other defect" requirement: pressure vessels typically have a rupture pressure that is 500% of MAWP.
- This sort of upgrade has been standard industry practice for a decade, without any venting related crisis in safety.

Other safety problems arise when we consider that of the many thousands of cargo tanks that would need to have new pressure relief valves fitted, some small portion of them will be replaced incorrectly, and result in unsafe valves being fitted to cargo tanks, or worse still, the tanks being inadvertently operated without safety relief devices at all.

Also, in this post September 11, 2001 environment, the confusion of throwing so many cargo tanks hauling hazardous materials in the United States into dubious legality will create opportunity for nefarious or terrorist agents to misuse these cargo tanks so as to utilize the hazardous nature of the commodity transported as a weapon against the public.

In light of these points, I urge you to revisit the clarification you offered up in your memo and alter it to agree with current industry practice and with Hattie Mitchell's 1996 clarification: Note that upgrades to DOT 400-series vents from MC 300-series vents must be of the entire venting system being replaced with one conforming to all of the requirements of §178.345-(10) including the set-to-discharge pressure of 120% MAWP and the flow rating at the tanks test pressure.

Also, in the same memo, you stated:

- ...  
Q1. A specification MC-307 cargo tank has a design pressure of 25 psig. Is it permissible to replace the original pressure actuated vent with a 400 series pressure relief device that will limit tank pressure to 130% of design pressure (32.5 psig) as required by § 178.342-2(b), but will not open until 30 psig?
- A1. No, a self closing pressure relief device set above a cargo tank's design pressure would allow the unit to be operated above its designed pressure which is in violation of § 180.407(a)(2). For example, an MC-307 cargo tank with a design pressure of 25 psig must have a pressure relief device which opens at 25 psig so to not allow the tank to continually operate over pressurized. The pressure relief device must be able to limit tank pressure to 130% of the design pressure.  
...

Utilizing the requirements of § 180.407(a)(2) to require that pressure relief device be set at the tanks test pressure would have the effect of making all DOT 407 tanks illegal. Section 180.407(a)(2) applies to all specification cargo tanks, not just MC 307 or other obsolete cargo tanks. DOT 400-series pressure relief vents are required by § 178.345-10(d) to be set to discharge at "no less than 120 percent of MAWP, and no more than 132 percent of MAWP." The only reasonable conclusion is that § 180.407(a)(2) is an operational limitation and not a guideline for setting pressure relief devices on specification cargo tanks.

Also, the requirement "The pressure relief device must be able to limit the tank pressure to 130% of the design pressure" stems from the venting requirements for MC-307 cargo tanks; see § 173.342-4(b). However, the provisions of §§ 173.33(d) and 180.405(c)(2) allow the upgrade of venting systems to the corresponding DOT 400-series venting systems. I submit that the only reasonable interpretation of these requirements is that §§ 173.33(d) and 180.405(c)(2) allow the appropriate venting sections supercede the venting requirements of obsolete specification cargo tank that is having its venting systems upgraded. Thus the requirements laid out for the original MC 307 cargo tank venting system in § 178.342-4 is superceded in its entirety by the venting requirements laid out in § 178.347-4 (which include the requirements of § 178.345-10) with the exception that the capacity requirements laid out in Table III still stand (this table is identical to the DOT 400-series Table I in § 178.345-10), and thus operators are cautioned against possibly fitting a venting system with insufficient capacity at the new pressures.

In light of these points, I ask if you could revisit your answer and change it to allow 25 psig MAWP MC 307 tanks to have their vents upgraded to DOT 407 vents having a set pressure of 30 psig as required by the requirements for DOT 407 vents as laid out in §178.345-10.

I'd like to thank you for your consideration of these points. If you have any questions, please feel free to contact me by phone, fax or e-mail and I would be happy to discuss or clarify any issues you may have.

Sincerely,

John Freiler  
Engineering Manager  
GIRARD EQUIPMENT, INC.

CC

Edward Mazzullo, Director, Office of Hazardous Materials Standards DHM-10, RSPA.

Fax:(202) 366-3012

William Quade, Division Chief, Hazardous Materials MC-ECH // M51200, FMCSA.

Fax:(202) 366-3462

Charles A. Horan, Office Director, Enforcement and Compliance MC-EC // M51000,

FMCSA. Fax:(202) 366-3462

Charles Hochman, Acting Director, Office of Hazardous Materials Technology DHM-20,

RSPA. Fax:(202) 366-3650

Ted Turner, Hazardous Materials Specialist. Fax:(614) 280-6875